PB89-222277

Small Quantity Generator's Handbook for Managing RCRA (Resource Conservation and Recovery Act) Wastes Wood Treating Industries

Science Applications International Corp., Bellevue, WA

Prepared for:

Environmental Protection Agency, Washington, DC

Jun 88

U.S. Department of Commerce
National Technical Information Service
NTIS

THE SMALL QUANTITY GENERATOR'S HANDBOOK FOR MANAGING RCRA WASTES

- WOOD TREATING INDUSTRIES -

STATE OF MONTANA
DEPARTMENT OF HEALTH AND ENVIRONMENTAL SCIENCES
HELENA, MONTANA

JUNE, 1988

50272-101

REPORT DOCUMENTATION PAGE	1. REPORT NO. 027-006 A	2.	PB89-222277

4. Title and Subtitle
The Small Quantity Generator's Handbook for Managing RCRA Wastes: Wood Treating Industries

5. Report Date
June 1988

6.

7. Author(s)

8. Performing Organization Rept. No.

9. Performing Organization Name and Address

Science Applications International Corporation
Environmental Technology Group
13400B Northrup Way
Suites 37, 38, 39
Bellevue, WA 98005

10. Project/Task/Work Unit No.
2-817-00-180

11. Contract(C) or Grant(G) No.
(C) 800329
(G)

12. Sponsoring Organization Name and Address

State of Montana
Department of Health and Environmental Sciences
Helena, Montana

13. Type of Report & Period Covered

14.

15. Supplementary Notes
This document is included in the Pollution Prevention Information Clearinghouse, operated by Science Applications International Corporation (SAIC) for the U.S. EPA, at 8400 Westpark Drive, McLean, Virginia 22102.

16. Abstract (Limit: 200 words)

(Resource Conservation and Recovery Act)

This RCRA Handbook was developed for pentachlorophenol and chromated copper arsenate wood treating businesses to assist them in complying with pertinent sections of the requirements. The sections describe facility operations and the wastes generated as a result of them; the hazardous wastes generated and the RCRA regulations that specifically apply to them; the RCRA generator requirements; and hazardous and non-hazardous waste management strategies for minimizing waste generation and handling waste. Appendices provide: information regarding the acute and toxic commercial chemical products and wastes (F, P, and U wastes); the procedures for identifying characteristic hazardous wastes in wood treating facilities; a list of references and contacts for obtaining additional information about hazardous wastes and their regulation.

17. Document Analysis a. Descriptors

pollution prevention

b. Identifiers/Open-Ended Terms

c. COSATI Field/Group

REPRODUCED BY
U.S. DEPARTMENT OF COMMERCE
NATIONAL TECHNICAL INFORMATION SERVICE
SPRINGFIELD, VA. 22161

18. Availability Statement	19. Security Class (This Report)	21. No. of Pages
Release unlimited		41
	20. Security Class (This Page)	22. Price

THE SMALL QUANTITY GENERATOR'S HANDBOOK FOR MANAGING RCRA WASTES

- WOOD TREATING INDUSTRIES -

Prepared for:

State of Montana
Department of Health and Environmental Sciences
Helena, Montana

Prepared by:

Science Applications International Corporation
Bellevue, Washington

Under Contract No. 800329
SAIC Ref. No. 2-817-00-180

June, 1988

This document was prepared by Science Applications International Corporation (SAIC) in support of the Waste Minimization Project. The workshops are co-sponsored by Montana Department of Health and Environmental Sciences (DHES) and the Montana Chamber of Commerce. Mention of any trade names or commercial products does not constitute endorsement or recommendation for use.

TABLE OF CONTENTS

		Page
1.0	INTRODUCTION	1
2.0	WASTE STREAM CHARACTERIZATION	3
	2.1 Summary of Operations	3
	2.2 Summary of Waste Streams	5
3.0	HAZARDOUS WASTE REGULATIONS	7
	3.1 Federal Hazardous Waste Regulations	7
	3.2 State Hazardous Waste Regulations	7
	3.3 Applicability of Federal and State Regulations to Wood Treatment Wastes	7
	3.4 Specific Regulations for Farmers	8
4.0	HAZARDOUS WASTE GENERATOR REQUIREMENTS	11
	4.1 Background	11
	4.2 Categories of Generators	11
	4.3 Requirements for All Generators	11
	4.4 Requirements for Conditionally Exempt Generators	13
	4.5 Requirements for Small Generators	14
5.0	WASTE MANAGEMENT PLANS	18
	5.1 Waste Minimization for PCP Wastes	18
	5.2 Minimization of CCA Wastes	21

APPENDIX A - List of Acute and Toxic Hazardous Wastes

APPENDIX B - Identifying RCRA Characteristic Hazardous Wastes

APPENDIX C - References and Contacts

1.0 INTRODUCTION

In 1976, Congress, recognizing that the problem of solid and hazardous waste disposal had become a national concern, passed the Resource Conservation and Recovery Act (RCRA). This legislation was designed to address two major problems:

- The dangers to human health and the environment posed by improper waste disposal.
- The conservation of valuable material and energy resources.

Subtitle C of RCRA establishes a "cradle-to-grave" hazardous waste management system, which is administered by the U.S. Environmental Protection Agency (U.S. EPA). This system provides for managing, tracking, and regulating hazardous wastes at each step of the way from generation to final disposal. The regulations developed by U.S. EPA apply to those who generate, transport, treat, store, or dispose hazardous wastes.

This RCRA Handbook was developed for pentachlorophenol and choramted copper arsenate wood treating businesses to assist them in complying with pertinent sections of the requirements. It provides procedures to minimize the costs of complying with the RCRA requirements by minimizing waste quantities and by focusing the facility manager's attention to those parts of the RCRA regulations that are relevant to normal operations at wood treating facilities.

The information on wood treating operations in this document was compiled through site visits to various types of wood treaters to identify hazardous and non-hazardous wastes and to observe current waste management procedures. Following these visits, a review of the RCRA requirements and Administrative Rules of Montana (ARM) was performed to identify specific regulations applicable to wood treatment facilities.

Section 2.0 of this manual describes facility operations and the wastes generated as a result of these operations. Section 3.0 discusses the hazardous wastes generated and the RCRA regulations that specifically apply to them. Section 4.0 discusses the RCRA generator requirements. Section

5.0 describes hazardous and non-hazardous waste management strategies for minimizing waste generation and handling waste. Appendix A provides information regarding the acute and toxic commercial chemical products and wastes (F, P, and U wastes). Appendix B describes the procedures for identifying characteristic hazardous wastes in wood treating facilities. Finally, Appendix C provides a list of references and contacts for obtaining additional information about hazardous wastes and their regulation.

2.0 WASTE STREAM CHARACTERIZATION

This section of the manual discusses wood preserving operations and generated waste streams. Covered in the handbook are pentachlorophenol and chrome-copper-arsenate wood treaters; commercial creosote treating operations do not exist in the state of Montana and are not covered in this handbook.

2.1 SUMMARY OF OPERATIONS

Wood treating is conducted to prevent wood from being attacked by various fungi and insects, as well as protecting it from rot due to excessive moisture penetration. Poles, timbers, and lumber are typically treated using one of several types of preservatives applied specifically for the type of use the wood is to receive. In Montana, pentachlorophenol (PCP) and chrome-copper-arsenate (CCA) are commonly used wood preservatives for treatment of poles and lumber. Three treatment processes are prevalent, regardless of the chemicals used. These include cold soaking, heat treatment, and pressure treatment. Of the three, pressure treatment is the least common method utilized in the state.

Where pentachlorophenol is used, it is bought in 2,000 pound blocks which are dissolved into a light oil carrier (usually diesel). Facilities may use three to seven blocks of PCP per year. This liquid is often stored in tanks prior to use. CCA is also bought in crystalline form and dissolved in water prior to use. CCA may also be stored in tanks.

2.1.1 Cold Soak Process

Steel dip tanks used for both cold soak and heat treatment processes vary in size from 3 to 10 feet wide, 25 feet long and 5 to 10 feet deep. Wood is set into a dip tank for 24 to 36 hours to allow the wood preserving solution to adequately penetrate the timber. The period of time may vary somewhat according to the charge (preservative penetration and retention) required by the customer. After soaking for the requisite period of time, the timbers are allowed to drip for an additional 24 hours. The dripping wood may be held over the tank during this time, or allowed to drip on a paved or

unpaved ground surface. After dripping, the timbers are sized and stored in piles. Storage of treated timbers generally occurs in open, unpaved storage yards.

2.1.2 Heat Treatment

Heat treatment is very similar to cold soaking, except that the treatment solution is heated to increase the quantity of preservative taken up and retained by the wood. PCP may be heated prior to its addition to the tank, or the PCP may be heated in the dip tank by coils under the tank prior to the wood being added. The wood is again soaked for a given period of time and allowed to drip following treatment. During the dripping period, heated PCP may volatilize or evaporate rather than drip.

2.1.3 Pressure Treatment

Pressure treatment utilizing PCP is conducted in a retort vessel, into which logs are placed. A vacuum is applied to the vessel, and PCP is introduced under pressure and allowed to soak into the wood. Soaking times for this type of treatment are much shorter than conventional cold or heat treatment processes, as the pressure utilized forces preservative into the wood at a greater rate and with better retention. Upon completion of treatment, the chemical is evacuated from the chamber and the wood pulled from the retort to drip. Wastes left in the bottom of the vessel may include water, emulsified treatment chemicals, and wood debris. This is periodically cleaned out of the treatment vessel.

2.1.4 CCA Treatment

CCA treatment of wood is similar to pressure treating wood with pentachlorophenol. However, CCA treatment of wood produces much less waste than PCP treatment. The timbers are placed in a retort vessel and a vacuum is applied. The CCA solution is introduced under pressure and allowed to soak into the wood. Upon completion of treatment, the chemical is evacuated from the chamber and the wood pulled from the retort to drip. Wastes left in the bottom of the vessel again include water, emulsified treatment chemicals, and wood debris. This waste is periodically cleaned out of the treatment vessel.

2.2 SUMMARY OF WASTE STREAMS

The waste streams for PCP wood treating may be separated into three components for all three processes used. These components include sludges, wastewater and emulsions, and waste PCP, all of which are produced in the dip tanks. Typically, the water and PCP are removed along with the sludge from the bottom of the dip tank. The three waste streams are discussed in greater detail below. Generally, CCA sludges are the only waste material generated from CCA wood treating.

2.2.1 Sludge

PCP Sludge - PCP sludge is generated from wood chips and dust that fall or are blown into the dip tank. Once in the tank, they eventually settle to the bottom. The quantity of sludge generated by a facility varies due to the type and quantity of wood treated and whether the tank is covered to reduce the opportunity for introduction of foreign material. Fifty to 200 gallons per year of sludge may be generated. The sludge consists primarily of water, emulsified PCP, coated wood chips, and dirt. Much of the water and oil may be separated from the sludge if it is allowed to sit undisturbed in some type of settling tank. Currently, many facilities containerize the sludge in 55-gallon drums. Other facilities dump the sludge into burn pits or use it for dust suppression on facility roads.

CCA Sludge - The CCA treatment process utilizes a closed system. The opportunity for the introduction of foreign material into the system is greatly reduced. Thus, very little sludge material is generated. The sludge consists primarily of wood debris saturated with water and CCA.

2.2.2 Waste PCP

Waste PCP is generated during cleaning of the dip tank to remove sludge. The sludge and PCP may be separated in a settling tank as discussed above. Usable PCP may be pumped back to a storage tank, leaving a small volume of PCP overlying the sludge. The second manner in which waste PCP is produced is as a result of water emulsions forming in the oil. This reduces the effectiveness and efficiency of the treatment process by reducing the concentration of the PCP. At some point, preferably when the volume of

preservative in the tank is low, the water-contaminated PCP mixture is removed and stored onsite in 55-gallon drums. Quantities of the waste oil and water mixture vary by facility from 50 to 200 gallons per year. Facilities that separate the mixture are often able to recover the PCP and place it back in the soak tank.

2.2.3 Wastewater

The wastewater that essentially contaminates the PCP mixture is a result of rain that enters an uncovered tank or moisture that is driven out of timbers during the heating process. The water then forms an emulsion with the oil, which prevents it from being easily evaporated from the mixture. This material is usually placed in a drum or settling tank where it separates from the sludge and oil to form the top layer of waste. Once the wastewater has separated, it is usually disposed on the ground or evaporated.

3.0 HAZARDOUS WASTE REGULATIONS

3.1 FEDERAL HAZARDOUS WASTE REGULATIONS

The Federal regulations governing the management of hazardous wastes are specified under the Resource Conservation and Recovery Act (RCRA). The objectives of RCRA are to improve the management of solid wastes, which includes hazardous wastes, to protect the environment and human health, and to conserve valuable materials and energy resources. These RCRA regulations are specified in the Code of Federal Regulations (CFR), Title 40, Parts 260 through 272. The Environmental Protection Agency has the authority to administer the RCRA program.

3.2 STATE HAZARDOUS WASTE REGULATIONS

In the State of Montana, the Department of Health and Environmental Science (DHES) has been given the authority from EPA to develop and administer a hazardous waste management program. EPA requires that the development and administration of this state program is consistent with the federal standards set forth in the RCRA regulations. The State has developed hazardous waste management regulations under the Montana Hazardous Waste Act of October 1, 1985, which are specified in the Administrative Rules of Montana, Title 16, Chapter 44. This state program incorporates the Federal RCRA standards and includes additional requirements that were developed for the classification, generation, storage, treatment, and disposal of hazardous wastes.

3.3 HAZARDOUS WASTE CLASSIFICATION

RCRA and the Administrative Rules of Montana (ARM) have established certain standards and criteria based on waste characteristics and management practices to determine whether or not a waste is considered a hazardous waste. If a waste is determined to be hazardous, specific regulations under RCRA and ARM apply to the management of that waste including storage, treatment, and disposal of the waste.

There are two ways a waste may be brought into the hazardous waste regulatory system: listing and identification through characteristics.

These classifications are summarized below:

- Listed Wastes - A waste may be considered hazardous if it appears on any one of four lists of hazardous wastes contained in the RCRA regulations. These wastes have been listed because they exhibit one of the characteristics described below or contain any number of toxic constituents that have been shown to be harmful to human health and the environment. The RCRA regulations list over 400 hazardous wastes, including wastes derived from non-specific sources (F Wastes), manufacturing processes (K Wastes), and discarded chemical products (P and U Wastes). These lists can be found in the CFR, Title 40, Part 261, Subpart D. The F, P, and U wastes are listed in Appendix A of this handbook.

- Characteristic Wastes - Even though a waste does not appear on one of the above hazardous waste lists, it may be considered a hazardous waste if it exhibits certain characteristics. A waste may be considered hazardous if it exhibits any one of the following characteristics: ignitable, corrosive, reactive, or EP toxic. These specific characteristics and criteria for identifying the RCRA characteristic wastes are described in detail in Appendix B. These characteristic wastes are referenced in the CFR, Title 40, Part 261, Subpart C.

3.4 APPLICABILITY OF FEDERAL AND STATE HAZARDOUS WASTE REGULATIONS TO WOOD TREATMENT WASTES

Wastes generated from wood treating operations may be subject to the RCRA and ARM hazardous waste regulations, depending upon their specific characteristics and how they are generated. The determination of applicable hazardous waste regulations to wood treatment wastes involves determining the types of wastes generated, their characteristics, and how they were generated. The following sections describe how wood treating wastes may be subject to the hazardous waste regulations based on these considerations.

3.4.1 Pentachlorophenol Wastes

The RCRA and ARM hazardous waste regulations pertaining to the classification of pentachlorophenol wastes are not well-defined and do not address all types of pentachlorophenol wastes that can be generated from wood treating operations. Currently, only the following types of pentachlorophenol wastes are addressed in the RCRA regulations:

- Unused formulations that contain pentachlorophenol are discarded are listed hazardous wastes with an EPA Hazardous Waste Number of F027. This does not refer to waste pentachlorophenol that is

generated during wood treating processes, but the pentachlorophenol used as a chemical feedstock.

- Some wood treating operations may conduct onsite treatment of process wastewaters. Sludges that are generated from these wastewater treatment operations are listed hazardous wastes with an EPA Hazardous Waste Number K001. Sludges that are generated in the process tanks are not included in this classification.

- PCP residues and contaminated soils resulting from the cleanup of a spill of PCP chemical feedstocks are classified as hazardous wastes [40 CFR 261.33]. This classification only refers to the PCP feedstocks, it does not apply to pentachlorophenol that is spilled from process tanks or drying areas.

- Waste PCP-in-oil mixtures may exhibit the characteristic of ignitability from the diesel carrier in the mixture.

If any of these four hazardous waste types are generated by a wood treater, there are specific requirements that must be met for the management of these wastes. These requirements are described in Section 4.0.

Specific types of pentachlorophenol wastes are not currently regulated under RCRA. These include: (1) waste pentachlorophenol generated during wood treating processes, such as that generated from changing a process tank; (2) The sludges containing pentachlorophenol that are generated in the process tanks; and (3) PCP residues and contaminated soils resulting from the cleanup of PCP from process tanks and drying areas. EPA is currently in the process of revising the RCRA regulations to include these waste types. These revised regulations are expected to become effective within the next few years.

Waste pentachlorophenol and sludges generated from the process tanks can be the major waste types generated from wood treating operations. Spillage of PCP from process tanks and drying areas are also common. Although these wastes are currently not addressed in the RCRA regulations, the waste pentachlorophenol and sludges from the process tanks, and spilled materials can exhibit the same hazardous characteristics as those PCP wastes that are regulated. For this reason, EPA and the Montana DHES strongly advise that these wastes be considered and managed as hazardous wastes. Section 4.0 of this document discusses the management of hazardous wastes as required by CRA and ARM.

3.4.2 Chromated Copper Arsenate Sludges

Chromated copper arsenate (CCA) sludges may exhibit the characteristic of EP toxicity due to its arsenic or chromium content. In order to determine whether this sludge is EP toxic, a representative sample of sludge should be collected and sent to an analytical laboratory for an EP toxicity test. If the sample is determined to be EP toxic, the sludge must be treated as hazardous waste and managed according to Section 4.0 of this manual. If the sludge is not tested, it should also be treated as a hazardous waste. Potential liability for mismanagement of hazardous wastes is too great to assume the sludge is not hazardous if not proven and documented to be non-hazardous.

4.0 HAZARDOUS WASTE GENERATOR REQUIREMENTS

4.1 BACKGROUND

The Environmental Protection Agency (EPA) and the Montana Department of Health and Environmental Science (DHES) classify generators of hazardous waste in three categories according to the amount of waste they generate. This classification was done in response to public attention to the fact the inappropriate management of even small quantities of hazardous waste can result in health or environmental problems. Depending on which generator category applies to a specific business, certain precautions or actions may be required in the management of hazardous wastes.

4.2 CATEGORIES OF GENERATORS

Businesses that generate 1,000 kilograms or more (2,200 pounds) per month of hazardous waste (or one kilogram per month of acute hazardous waste) must abide by all of the requirements of the law, and are not eligible for any exemptions. These are classified as large hazardous waste generators. Requirements for this category are not addressed in this manual.

Businesses generating between 100 kilograms and 1,000 kilograms (220 pounds to 2,200 pounds) per month of hazardous waste have been designated as **SMALL GENERATORS** and are allowed some special provisions. Finally, businesses that generate less than 100 kilograms (220 pounds) per month of hazardous waste are designated as **CONDITIONALLY EXEMPT GENERATORS**.

4.3 REQUIREMENTS FOR ALL GENERATORS

Each of the requirements that are described below apply to all generators, regardless of quantity. These are summaries of the Federal regulations and the State of Montana's regulations. The Federal regulations for hazardous waste generators are found in the Code of Federal Regulations, Title 40, Parts 261 and 262 (40 CFR 261 and 262) and are administered by EPA. The State of Montana's rules for hazardous waste generators are found in the Administrative Rules of Montana, Title 16, Chapter 44, and administered by DHES.

It is important to note that the Federal laws apply nationwide. In some cases, requirements that have been added to the original Federal laws have not yet been adopted by the State of Montana. Even if the State has not yet adopted certain requirements from the Federal law, businesses are still required to abide by these Federal requirements. In addition, the State of Montana may have developed special requirements to address special problems within the state.

- All generators must determine which of the wastes they generate are hazardous. Sections 2.0 and 3.0 of this guidance manual contains descriptions of the hazardous wastes generated in a specific type of business. [40 CFR 262.11, ARM 16.44.402]

- All generators must segregate <u>listed</u> (F, K, P and U) hazardous wastes from non-hazardous wastes. Listed hazardous wastes are materials that have been specifically catalogued and are always considered hazardous. MIXING THESE WASTES WITH NON-HAZARDOUS WASTE WILL MAKE THE ENTIRE VOLUME A HAZARDOUS WASTE. Sections 2.0 and 3.0 of this guidance manual identified listed hazardous wastes that may be generated in your business. The F, P, and U wastes are listed in Appendix A.

- Under certain circumstances, generators may mix characteristic hazardous wastes and non-hazardous wastes if they are compatible (not reactive or explosive, etc.). The mixture is considered non-hazardous only if it no longer meets the characteristics of a hazardous waste. IF THE MIXTURE IS A WASTE EXHIBITING A HAZARDOUS CHARACTERISTIC, THE ENTIRE MIXTURE BECOMES A HAZARDOUS WASTE, AND THE SMALL GENERATOR MAY BECOME A LARGE GENERATOR AS A RESULT. Section 3.0 and Appendix B of this guidance manual identify the characteristics of hazardous waste that may apply to your business.

- In the event of a hazardous waste spill, all generators must treat spilled hazardous wastes, clean-up residues, and containers as hazardous wastes.

- All generators must use containers that are compatible with the hazardous waste they are to contain. Containers should be sealed and free from leakage.

- All generators of hazardous waste must ensure their wastes are delivered to an off-site facility that is authorized by EPA or the state in which the receiving facility is located to receive municipal, industrial, or hazardous waste. The type of facility depends on the category of the generator.

- All generators must ensure that off-site shipments of hazardous waste are labeled, marked, and placarded according the U.S. Department of Transportation (DOT) requirements. This includes a U.S. DOT waste description, shipping name, hazard class, and

identification number. Any questions about DOT shipping requirements can be referred to the Montana State Department of Transportation. [40 CFR 262.30 to 262.33]

- A Hazardous Waste Manifest is required when shipping hazardous wastes off-site. The standard form is the U.S. EPA manifest form 8700-22, which is processed by DHES. [ARM 16.44.405]

4.4 REQUIREMENTS FOR CONDITIONALLY EXEMPT GENERATORS

A business qualifies as a Conditionally Exempt Generator if no more than 100 kilograms (220 pounds) per month of hazardous waste and no more than 1 kilogram (2.2 pounds) per month of acutely hazardous waste are generated. Acutely hazardous wastes are listed in Table A-1 of Appendix A. No more than 1,000 kilograms (2,200 pounds) of hazardous waste can be accumulated on-site or on your property. There is no time limit for this accumulation, as long as the 1,000 kilogram storage limit is not exceeded.

As a rule of thumb, a 55-gallon drum of hazardous waste is about 200 kilograms (440 pounds). This means that the business must generate less than one-half of a 55-gallon drum of hazardous waste per month or accumulate no more than five 55-gallon drums at any one time.

As long as the above two conditions are maintained, a business falls into a category called "conditionally exempt". The business must still meet all of the requirements presented in Section 4.3 of this manual, but it is conditionally exempt from other requirements for generators of hazardous wastes.

Examples of how a business can lose conditionally exempt status are:

- The business generates less than 100 kilograms per month eleven months out of the year, and more than 100 kilograms in the twelfth month.
- The amount of hazardous waste accumulated by a business exceeds 1,000 kilograms.

If hazardous waste management practices result in a business losing its conditionally exempt status, all requirements for Small Generators must be met. These are listed in Section 4.5 of this manual.

As long as the business meets the requirements of this section, hazardous waste may be disposed at a hazardous waste facility, or a licensed Class II sanitary landfill or other facility approved by the State of Montana for industrial or municipal wastes, on the condition that the operating authority of the landfill accepts the waste.

4.5 REQUIREMENTS FOR SMALL GENERATORS

Small generators are businesses generating between 100 and 1,000 kilograms (220 to 2,200 pounds) of hazardous waste per month. If a business falls in this category, it also may not generate more than 1 kilogram (2.2 pounds) per month of acutely hazardous waste (see Appendix A, Table A-1 and Section 3.3), and may not accumulate on-site more than 6,000 kilograms of hazardous waste. Businesses in this category must meet the following requirements:

Identification

- Small generators must have an EPA identification number. This twelve-digit number is part of a national data base to track hazardous waste activities for generators, transporters, disposal facilities, etc. In order to obtain an EPA identification number, contact the State of Montana Department of Health and Environmental Sciences and request a copy of EPA form 8700-12 "Notification of Hazardous Waste Activity". [40 CFR 262.12, ARM 16.44.403]

Accumulation Time Limit

- Storage of hazardous waste on the generator's property must not exceed 180 days, except if the waste must be transported greater than 200 miles, in which case the waste may be stored for up to 270 days. Hazardous waste may only be transported to authorized treatment, storage, or disposal facilities (TSDF). DHES can assist businesses with locating an authorized facility. This provision is designed to allow Small Generators to accumulate enough waste to justify making a shipment. [40 CFR 262.34 (e-f), ARM 16.44.415]

- Containers or drums must be labeled and dated on the first day that any hazardous waste is placed in them. From this date, each individual container may hold waste for a maximum of 180 days (or 270 days, depending on shipping distance) before it must be shipped to a TSDF. Wastes may not be transferred from one container to another to extend the allowable accumulation time. [40 CFR 262.34, ARM 16.44.415]

- Small Generators who reach the 6,000 kilogram (13,200 pounds) accumulation limit for total hazardous wastes on site must ship the waste to a TSDF in accordance with the rules in this section.

On-site Treatment

- Under certain circumstances, Small Generators may treat hazardous wastes on their property without a special permit only if the treatment takes place within the 180 day (or 270 day) time limit for storage and only if all container and tank storage requirements presented below are followed, and all necessary precautions taken to prevent spills or accidents. On-site treatment should be discussed with Montana DHES prior to commencement of operations to ensure that all applicable regulations have been followed.

On-site Disposal

- No Small Generator may dispose of hazardous wastes on their property without a **Disposal Permit** issued by EPA or DHES.

Shipment

- Small Generators must ship wastes to a hazardous waste TSDF. Wastes must be shipped using a manifest, and all manifest and waste analysis records must be maintained for at least three years. Care should be taken in selecting a waste hauler and a TSDF since the generator is **still responsible** for the proper management of the waste, even after it leaves his property. The generator should ensure that all hazardous waste haulers and TSDFs have EPA ID numbers. [40 CFR 262.40, 262.44, ARM 16.44.416]

Container Storage

If hazardous wastes are stored in containers (such as drums) the generator must:

- Clearly label each container with the words "Hazardous Waste" and the date on which waste storage begins in that container. Labels can be obtained from DHES.

- Make sure that hazardous waste is not stored in a container that will be corroded, ruptured, or damaged in any way by that waste. [40 CFR 265.172]

- Containers should be closed except when being filled or emptied. [40 CFR 265.173]

- Inspect containers weekly. Keep containers in good shape and replace any that are leaking. [40 CFR 265.174]

- Transfer hazardous waste from leaking containers to different containers. Label the new containers with the start date from the original container. [40 CFR 265.171]

- Never store wastes in the same container if they are non-compatible (reactive, explosive, etc.). [40 CFR 265.177]

- Containers of ignitable or reactive wastes must be stored as far as possible from the facility property line to ensure a buffer zone.

Tank Storage

If hazardous wastes are stored in tanks the generator must:
[40 CFR 265.201]

- Inspect tanks weekly and ensure that they are not leaking. Inspect monitoring or gauging systems each operating day.

- Make sure that hazardous waste is not stored in a tank that will be corroded, ruptured, or damaged in any way by that waste.

- Keep the tank covered or maintain at least two feet of freeboard (space at the top of the tank) in uncovered tanks.

- Provide a means to cut off or divert flow of waste into the tank in the event of a problem.

- Abide by National Fire Protection Association requirements for tanks containing ignitable or reactive wastes. These requirements specify the distances needed to establish safe buffer zones for various liquids based on combustible and flammable characteristics. The local fire department or DHES can assist with this.

Emergency Response

- At least one employee must be on hand or on call at all times in case of an emergency, and to be responsible for coordinating emergency response measures. This person is the emergency coordinator and he or his designee must respond to any emergencies.

- Small Generators must post the following information next to the telephone:

  - Name and telephone number of the emergency coordinator

  - Location of the fire extinguishers, spill control equipment, and fire alarm

  - Telephone number of the fire department, unless the facility is equipped with a direct alarm

- Small Generators must ensure that all employees are thoroughly familiar with the waste handling and emergency procedures relevant to their responsibilities.

- Emergencies that require a response include the following:

  - In the event of a fire, call the fire department or attempt extinguish the fire using a fire extinguisher

  - In the event of a spill, contain the flow of hazardous waste to the extent possible, and as soon as is practicable, clean up the hazardous waste and any contaminated materials or soil

- In the event of a fire, explosion, or other release that could threaten human health outside the facility or when the generator has knowledge that a spill has reached surface waters, the generator must immediately notify both the Montana DHES Hazardous Materials Spills Program (1-406-444-6911) and the National Response Center (1-800-424-8802). The report must include the following:

  - The generator's name, address, and EPA identification number

  - Date, time, and type of accident (e.g., spill, fire)

  - Quantity and type of hazardous waste involved in the incident

  - Extent of injuries, if any

  - Estimated quantity and disposition of recovered materials, if any

5.0 WASTE MANAGEMENT PLANS

This section of the manual provides waste management strategies currently available to the wood preservers. Waste management strategies are focused on minimizing the amount of hazardous waste that could be generated from these operations. There are several advantages of hazardous waste minimization. These include:

- Reducing the high costs associated with the management and disposal of hazardous wastes.
- Reducing the liability risks associated with the management and disposal of hazardous wastes.
- Reducing the problems arising from restrictions on land disposal of certain hazardous wastes.
- Minimizing the time and resources required to comply with the hazardous waste management regulations.

Waste minimization practices can include product substitution, process modifications, waste treatment, good housekeeping practices, and recycling and reuse. The selection of a particular waste minimization practice is based upon the industry or business operations, types of wastes generated, and their individual needs and problems.

The waste management strategies presented in the sections which follow are based upon practices currently in use in the wood preserving industry. The selected strategies will allow the wood treater to meet the RCRA and ARM hazardous waste conditionally exempt and small generator requirements.

5.1 WASTE MINIMIZATION FOR PCP WASTES

5.1.1 Settling Tanks

Settling tanks may be employed by a facility to reduce the volume of waste material that must be disposed as hazardous waste. A settling tank will allow the waste to separate into three components including water, reuseable PCP, and sludge. The water layer should be removed and placed in an empty container that will eventually be used to store sludge. The water should be

evaporated and any hazardous residues which remain in the barrel can be disposed along with the sludge.

The PCP can be removed from the tank after the top water layer has been removed and should be placed back in the soak tank. A spigot installed near the bottom of the tank may also be helpful to remove the PCP which has separated from the water and sludge. The spigot will allow the PCP to be removed without first removing the overlying water layer. The spigot should be installed near enough to the bottom of the tank to maximize the amount of oil which may be drawn. One method that can be used to minimize the amount of water drawn out with the oil is to use a yard stick to measure the thickness of the three levels of waste. From this information, and knowing where the discharge valve is in relation to the top of the oil layer, the volume of water-free oil that may be removed can be calculated. Once the layers of water and PCP have been removed, the sludge may be removed and stored in 55-gallon drums or other approved containers.

If a facility generates significant quantities of sludge, it is suggested that the settling tank be of sufficient volume to produce approximately a 55-gallon drum of sludge when the sludge is removed. This is suggested because the separation of the waste into its three components is time consuming and there are time constraints on the storage of hazardous wastes. For example, suppose ten gallons of sludge that took 100 days to settle were removed from a settling tank and placed in a drum. In 180 or 270 days this waste would require disposal. Although, additional sludge could be added to the drum, a partially filled drum would still require disposal. Thus, from an economic standpoint, it would be advantageous to dispose of a full 55-gallon drum rather than a portion of one. Using a settling tank of sufficient volume allows for the addition of several batches of waste to accumulate enough sludge in the settling tank for more economic disposal. Remember to stay within the onsite storage requirements for conditionally exempt and small generators as discussed in Section 4.0.

5.1.2 Water Minimization

Minimizing the amount of water which enters the soak tank will also reduce the amount of sludge produced. Water enhances the development of sludge by

lowering the viscosity and density of the oil which allows suspended material to settle more easily. It also produces oil-water emulsions which are carried to the bottom of the tank along with dirt and wood chips. Keeping the soak tank covered and using timbers with a minimal amount of water will reduce the amount of sludge produced.

Keeping a cover on the soak tank reduces the amount of wind blown material, such as dust and wood chips, that may enter the tank and produce sludge. Similarly, this will also help to minimize the amount of water which may enter the tank during periods of rain. Some wood preservers will not treat wood on rainy days due to the high humidity content in the air and the necessary removal of tank covers in the rain. Both add additional moisture content to the PCP.

The use of low moisture wood will also reduce the quantity of water generated during thermal treatment. The water in the timbers is driven from the timbers during heating. Using a more thoroughly dried wood for treatment will reduce the amount of sludge generated.

5.1.3 Spill Material

Minimizing the amount of waste material spilled on the ground from drip drying treated wood will also reduce the amount of hazardous waste generated. The drying of timbers next to the soak tank will require that PCP or CCA spilled on the ground and any contaminated soil be promptly excavated and containerized. The spilled material must be managed as a hazardous waste.

To reduce the amount of spillage produced, treated timbers should either be dried in the soak tank or suspended above the tank for drying. In some instances, it may be effective to construct a wind break to reduce the amount of wind blown material produced. Facilities whose production schedule prohibits prolonged drying of treated timbers suspended over the soak tank may need to consider the construction of a concrete pad. Timbers may drip over the pad and the material should be absorbed with vermiculite or cat litter. This contaminated absorbent may be added to the sludge for disposal as a hazardous waste. Although an absorbent is still required to

clean up spills, it generates significantly less waste material than the excavation of contaminated soils. The cost of construction of an adequately sized concrete pad should be compared to that of the long-term disposal of contaminated soil.

5.2 MINIMIZATION OF CCA WASTES

The CCA process generates far fewer wastes than the PCP treating processes. Because the system essentially operates as a closed loop, very few liquids are wasted following treatment. However, for liquids that are wasted, many of the minimization processes identified above for PCP can be used and should be investigated.

CCA Sludges

CCA sludges may be minimized primarily by having them tested for EP toxicity to determine if they must be treated as hazardous waste. If they are not EP toxic, they may be disposed at a licensed Class II sanitary landfill only if the generator receives the permission of the owner/operator of the landfill, and disposal is conducted in an environmentally safe manner. In some cases, CCA sludges may be dried to remove water, thus minimizing the volume of sludge to be disposed as a hazardous waste. Where possible, any evacuated liquids should be removed from the retorts and pumped back into storage tanks for re-use.

Appendix A

LIST OF ACUTE AND TOXIC HAZARDOUS WASTES

Table A-1

LIST OF ACUTE HAZARDOUS WASTES
Source: 40 CFR 261.33(e)

Hazardous waste No.	Chemical Abstracts No.	Substance
P023	107-20-0	Acetaldehyde, chloro-
P002	591-08-2	Acetamide, N-(aminothioxomethyl)-
P057	640-19-7	Acetamide, 2-fluoro-
P058	62-74-8	Acetic acid, fluoro-, sodium salt
P066	16752-77-5	Acetimidic acid, N-[(methylcarbamoyl)oxy] thio-, methyl ester
P002	591-08-2	1-Acetyl-2-thiourea
P009	131-74-8	Ammonium picrate (R)
P119	7803-55-6	Ammonium vanadate
P010	7778-39-4	Arsenic acid
P012	1327-53-3	Arsenic oxide As_2
P011	1303-28-2	Arsenic oxide As_2O_5
P011	1303-28-2	Arsenic pentoxide
P012	1327-53-3	Arsenic trioxide
P038	692-42-2	Arsine, diethyl-
P036	696-28-6	Arsonous dichloride, phenyl-
P054	151-56-4	Aziridine
P013	542-62-1	Barium cyanide
P024	106-47-8	Benzenamine, 4-chloro-
P077	100-01-6	Benzenamine, 4-nitro-
P028	100-44-7	Benzene, (chloromethyl)-
P042	51-43-4	1,2-Benzenediol, 4-[1-hydroxy-2-(methylamino)ethyl]-, (R)
P046	122-09-8	Benzeneethanamine, alpha,alpha-dimethyl-
P014	108-98-5	Benzenethiol
P001	[1]81-81-2	2H-1-Benzopyran-2-one, 4-hydroxy-3-(3-oxo-1-phenylbutyl)-, and salts
P028	100-44-7	Benzyl chloride
P015	7440-41-7	Beryllium dust
P016	542-88-1	Bis(chloromethyl) ether
P017	598-31-2	Bromoacetone
P018	357-57-3	Brucine
P021	592-01-8	Calcium cyanide
P022	75-15-0	Carbon bisulfide
P022	75-15-0	Carbon disulfide
P095	75-44-5	Carbonic dichloride
P023	107-20-0	Chloroacetaldehyde
P024	106-47-8	p-Chloroaniline
P029	544-92-3	Copper cyanide
P030	——	Cyanides (soluble cyanide salts), not otherwise specified
P031	460-19-5	Cyanogen
P033	506-77-4	Cyanogen chloride
P034	131-89-5	2-Cyclohexyl-4,6-dinitrophenol
P036	696-28-6	Dichlorophenylarsine
P037	60-57-1	Dieldrin
P038	692-42-2	Diethylarsine
P041	311-45-5	Diethyl-p-nitrophenyl phosphate
P040	297-97-2	O,O-Diethyl O-pyrazinyl phosphorothioate
P043	55-91-4	Diisopropyl fluorophosphate (DEP)
P004	309-00-2	1,4:5,8-Dimethanonaphthalene, 1,2,3,4,10,10-hexachloro-1,4,4a,5,8,8a-hexahydro-, (1alpha,4alpha,4abeta,5alpha, 8alpha,8abeta)-
P003	107-02-8	Acrolein
P070	116-06-3	Aldicarb
P004	309-00-2	Aldrin
P005	107-18-6	Allyl alcohol
P006	20859-73-8	Aluminum phosphide (R,T)
P007	2763-96-4	5-(Aminomethyl)-3-isoxazolol
P008	504-24-5	4-alpha-Aminopyridine
P046	122-09-8	alpha, alpha-Dimethylphenethylamine
P047	[1]534-52-1	4,6-Dinitro-o-cresol and salts
P048	51-28-5	2,4-Dinitrophenol
P020	88-85-7	Dinoseb
P085	152-16-9	Diphosphoramide, octamethyl-
P039	298-04-4	Disulfoton
P049	541-53-7	2,4-Dithiobiuret
P050	115-29-7	Endosulfan
P088	145-73-3	Endothal
P051	72-20-8	Endrin
P042	51-43-4	Epinephrine
P101	107-12-0	Ethyl cyanide
P054	151-56-4	Ethyleneimine
P097	52-85-7	Famphur
P056	7782-41-4	Fluorine
P057	640-19-7	Fluoroacetamide
P058	62-74-8	Fluoroacetic acid, sodium salt
P065	628-86-4	Fulminic acid, mercury(2+)salt (R,T)
P059	76-44-8	Heptachlor
P062	757-58-4	Hexaethyltetraphosphate
P116	79-19-6	Hydrazinecarbothioamide
P068	60-34-4	Hydrazine, methyl-
P063	74-90-8	Hydrocyanic acid
P063	74-90-8	Hydrogen cyanide
P096	7803-51-2	Hydrogen phosphide
P064	624-83-9	Isocyanic acid, methyl ester
P060	465-73-6	Isodrin
P007	2763-96-4	3(2H)-Isoxazolone, 5-(aminomethyl)-
P092	62-38-4	Mercury, (acetato-O)phenyl-
P065	628-86-4	Mercury fulminate (R,T)
P082	62-75-9	Methanamine, N-methyl-N-nitroso-
P016	542-88-1	Methane, oxybis(chloro-
P112	509-14-8	Methane, tetranitro- (R)
P118	75-70-7	Methanethiol, trichloro-
P050	115-29-7	6,9-Methano-2,4,3-benzodioxathiepen, 6,7,8,9,10,10-hexachloro-1,5,5a,6,9,9a-hexahydro-, 3-oxide
P059	76-44-8	4,7-Methano-1H-indene, 1,4,5,6,7,8,8-heptachloro-3a,4,7,7a-tetrahydro-
P066	16752-77-5	Methomyl
P067	75-55-8	2-Methylaziridine
P068	60-34-4	Methyl hydrazine
P064	624-83-9	Methyl isocyanate
P069	75-86-5	2-Methyllactonitrile
P071	298-00-0	Methyl parathion
P072	86-88-4	alpha-Naphthylthiourea

Table A-1 (cont'd)

Hazardous waste No.	Chemical Abstracts No.	Substance
P060	465-73-6	1,4:5,8-Dimethanonaphthalene, 1,2,3,4,10,10-hexachloro-1,4,4a,5,8,8a-hexahydro-, (1alpha,4alpha,4abeta,5beta,8beta,8abeta)-
P037	60-57-1	2,7:3,6-Dimethanonaphth[2,3b]oxirane, 3,4,5,6,9,9-hexachloro-1a,2,2a,3,6,6a,7,7a-octahydro-, (1aalpha,2beta,2aalpha,3beta,6beta,6aalpha,7beta,7aalpha)-
P051	72-20-8	2,7:3,6-Dimethanonaphth[2,3b]oxirane, octahydro-, (1aalpha,2beta,2abeta,3alpha,6alpha,6abeta,7beta,7aalpha)-
P044	60-51-5	Dimethoate
P045	39196-18-4	3,3-Dimethyl-1-(methylthio)-2-butanone, O-[(methylamino)carbonyl] oxime
P085	152-16-9	Octamethylpyrophosphoramide
P087	20816-12-0	Osmium oxide
P087	20816-12-0	Osmium tetroxide
P088	145-73-3	7-Oxabicyclo[2.2.1]heptane-2,3-dicarboxylic acid
P089	56-38-2	Parathion
P034	131-89-5	Phenol, 2-cyclohexyl-4,6-dinitro-
P048	51-28-5	Phenol, 2,4-dinitro-
P047	[1]534-52-1	Phenol, 2-methyl-4,6-dinitro- and salts
P020	88-85-7	Phenol, 2-(1-methylpropyl)-4,6-dinitro-
P009	131-74-8	Phenol, 2,4,6-trinitro-, ammonium salt (R)
P092	62-38-4	Phenylmercury acetate
P093	103-85-5	Phenylthiourea
P094	298-02-2	Phorate
P095	75-44-5	Phosgene
P096	7803-51-2	Phosphine
P041	311-45-5	Phosphoric acid, diethyl 4-nitrophenyl ester
P039	298-04-4	Phosphorodithioic acid, O,O-diethyl S-[2-(ethylthio)ethyl] ester
P094	298-02-2	Phosphorodithioic acid, O,O-diethyl S-[(ethylthio)methyl] ester
P044	60-51-5	Phosphorodithioic acid, O,O-dimethyl S[2-(methylamino)-2-oxoethyl] ester
P043	55-91-4	Phosphorofluoridic acid, bis(1-methylethyl) ester
P089	56-38-2	Phosphorothioic acid, O,O-diethyl O-(p-nitrophenyl) ester
P040	297-97-2	Phosphorothioic acid, O,O-diethyl O-pyrazinyl ester
P097	52-85-7	Phosphorothioic acid, O-[4-((dimethylamino)-sulfonyl)phenyl] O,O-dimethyl ester
P071	298-00-0	Phosphorothioic acid, O,O-dimethyl O-(4-nitrophenyl) ester
P110	78-00-2	Plumbane, tetraethyl-
P098	151-50-8	Potassium cyanide
P099	506-61-6	Potassium silver cyanide
P070	116-06-3	Propanal, 2-methyl-2-(methylthio)-, O-[(methylamino)carbonyl]oxime
P101	107-12-0	Propanenitrile
P027	542-76-7	Propanenitrile, 3-chloro-
P069	75-86-5	Propanenitrile, 2-hydroxy-2-methyl-
P081	55-63-0	1,2,3-Propanetriol, trinitrate (R)
P017	598-31-2	2-Propanone, 1-bromo-
P102	107-19-7	Propargyl alcohol
P003	107-02-8	2-Propenal
P073	13463-39-3	Nickel carbonyl
P073	13463-39-3	Nickel carbonyl, (T-4)-
P075	[1]54-11-5	Nicotine and salts
P076	10102-43-9	Nitric oxide
P077	100-01-6	p-Nitroaniline
P078	10102-44-0	Nitrogen dioxide
P076	10102-43-9	Nitrogen oxide NO
P078	10102-44-0	Nitrogen oxide NO_2
P081	55-63-0	Nitroglycerine (R)
P082	62-75-9	N-Nitrosodimethylamine
P084	4549-40-0	N-Nitrosomethylvinylamine
P074	557-19-7	Nickel cyanide
P005	107-18-6	2-Propen-1-ol
P067	75-55-8	1,2-Propylenimine
P102	591-08-2	2-Propyn-1-ol
P008	504-24-5	Pyridinamine
P075	[1]54-11-5	Pyridine, (S)-3-(1-methyl-2-pyrrolidinyl)-, and salts
P111	107-49-3	Pyrophosphoric acid, tetraethyl ester
P103	630-10-4	Selenourea
P104	506-64-9	Silver cyanide
P105	26628-22-8	Sodium azide
P106	143-33-9	Sodium cyanide
P107	1314-96-1	Strontium sulfide
P108	[1]57-24-9	Strychnidin-10-one, and salts
P018	357-57-3	Strychnidin-10-one, 2,3-dimethoxy-
P108	[1]57-24-9	Strychnine and salts
P115	10031-59-1	Sulfuric acid, thallium(I) salt
P109	3689-24-5	Tetraethyldithiopyrophosphate
P110	78-00-2	Tetraethyl lead
P111	107-49-3	Tetraethylpyrophosphate
P112	509-14-8	Tetranitromethane (R)
P062	757-58-4	Tetraphosphoric acid, hexaethyl ester
P113	1314-32-5	Thallic oxide
P113	1314-32-5	Thallium(III) oxide
P114	12039-52-0	Thallium(I) selenide
P115	10031-59-1	Thallium(I) sulfate
P109	3689-24-5	Thiodiphosphoric acid, tetraethyl ester
P045	39196-18-4	Thiofanox
P049	541-53-7	Thioimidodicarbonic diamide
P014	108-98-5	Thiophenol
P116	79-19-6	Thiosemicarbazide
P026	5344-82-1	Thiourea, (2-chlorophenyl)-
P072	86-88-4	Thiourea, 1-naphthalenyl-
P093	103-85-5	Thiourea, phenyl-
P123	8001-35-2	Toxaphene
P118	75-70-7	Trichloromethanethiol
P119	7803-55-6	Vanadic acid, ammonium salt
P120	1314-62-1	Vanadium(V) oxide
P084	4549-40-0	Vinylamine, N-methyl-N-nitroso-
P001	81-81-2	Warfarin
P121	557-21-1	Zinc cyanide
P122	1314-84-7	Zinc phosphide (R,T)

[1]CAS Number given for parent compound only.

Table A-1 (cont'd)

Industry and EPA hazardous waste No.	Hazardous waste	Hazard code
F020	Wastes (except wastewater and spent carbon from hydrogen chloride purification) from the production or manufacturing use (as a reactant, chemical intermediate, or component in a formulating process) of tri- or tetrachlorophenol, or of intermediates used to produce their pesticide derivatives. (This listing does not include wastes from the production of Hexachlorophene from highly purified 2,4,5-trichlorophenol.).	(H)
F021	Wastes (except wastewater and spent carbon from hydrogen chloride purification) from the production or manufacturing use (as a reactant, chemical intermediate, or component in a formulating process) of pentachlorophenol, or of intermediates used to produce its derivatives.	(H)
F022	Wastes (except wastewater and spent carbon from hydrogen chloride purification) from the manufacturing use (as a reactant, chemical intermediate, or component in a formulating process) of tetra- , penta-, or hexachlorobenzenes under alkaline conditions.	(H)
F023	Wastes (except wastewater and spent carbon from hydrogen chloride purification) from the production of materials on equipment previously used for the production or manufacturing use (as a reactant, chemical intermediate, or component in a formulating process) of tri- and tetrachlorophenols. (This listing does not include wastes from equipment used only for the production or use of Hexachlorophene from highly purified 2,4,5-trichlorophenol.).	(H)
F026	Wastes (except wastewater and spent carbon from hydrogen chloride purification) from the production of materials on equipment previously used for the manufacturing use (as a reactant, chemical intermediate, or component in a formulating process) of tetra-, penta-, or hexachlorobenzene under alkaline conditions.	(H)
F027	Discarded unused formulations containing tri-, tetra-, or pentachlorophenol or discarded unused formulations containing compounds derived from these chlorophenols. (This listing does not include formulations containing Hexachlorophene sythesized from prepurified 2,4,5-trichlorophenol as the sole component.).	(H)

Table A-2

LIST OF TOXIC WASTES
Source: 40 CFR 261.33(f)

Hazardous waste No.	Chemical Abstracts No.	Substance
U001	75-07-0	Acetaldehyde (I)
U034	75-87-6	Acetaldehyde, trichloro-
U187	62-44-2	Acetamide, N-(4-ethoxyphenyl)-
U005	53-96-3	Acetamide, N-9H-fluoren-2-yl-
U112	141-78-6	Acetic acid, ethyl ester (I)
U144	301-04-2	Acetic acid, lead salt
U214	563-68-8	Acetic acid, thallium (1+) salt
U232	93-76-5	Acetic acid, (2,4,5,-trichlorophenoxy)-
U002	67-64-1	Acetone (I)
U003	75-05-8	Acetonitrile (I,T)
U004	98-86-2	Acetophenone
U005	53-96-3	2-Acetylaminofluorene
U006	75-36-5	Acetyl chloride (C,R,T)
U007	79-06-1	Acrylamide
U008	79-10-7	Acrylic acid(I)
U009	107-13-1	Acrylonitrile
U011	61-82-5	Amitrole
U012	62-53-3	Aniline (I,T)
U014	492-80-8	Auramine
U015	115-02-6	Azaserine
U010	50-07-7	Azirino(2',3':3,4)pyrrolo(1,2-a]indole-4,7-dione,6-amino-8-[((aminocarbonyl)oxy) methyl]-1,1a,2,8,8a,8b-hexahydro-8a-methoxy-5-methyl-
U157	50-49-5	Benz[j]aceanthrylene, 1,2-dihydro-3-methyl-
U016	225-51-4	3,4-Benzacridine
U017	98-87-3	Benzal chloride
U192	23950-58-5	Benzamide, 3,5-dichloro-N-(1,1-diethyl-2-propynyl)-
U018	56-55-3	Benz[a]anthracene
U094	57-97-6	Benz[a]anthracene, 7,12-dimethyl-
U012	62-53-3	Benzenamine (I,T)
U014	492-80-8	Benzenamine, 4,4'-carbonimidoylbis[N,N-dimethyl-
U049	3165-93-3	Benzenamine, 4-chloro-2-methyl-
U093	60-11-7	Benzenamine, N,N-dimethyl-4-(phenylazo)-
U328	95-53-4	Benzenamine, 2-methyl-
U353	106-49-0	Benzenamine, 4-methyl-
U158	101-14-4	Benzenamine, 4,4'-methylenebis[2-chloro-
U222	636-21-5	Benzenamine, 2-methyl-, hydrochloride
U181	99-55-8	Benzenamine, 2-methyl-5-nitro-
U019	71-43-2	Benzene
U038	510-15-6	Benzeneacetic acid, 4-chloro-alpha-(4-chlorophenyl)-alpha-hydroxy, ethyl ester
U030	101-55-3	Benzene, 1-bromo-4-phenoxy-
U035	305-03-3	Benzenebutanoic acid, 4-[bis(2-chloroethyl)amino]-
U037	108-90-7	Benzene, chloro-
U221	25376-45-8	Benzenediamine, ar-methyl-
U028	117-81-7	1,2-Benzenedicarboxylic acid, [bis(2-ethylhexyl)] ester
U069	84-74-2	1,2-Benzenedicarboxylic acid, dibutyl ester
U088	84-66-2	1,2-Benzenedicarboxylic acid, diethyl ester
U102	131-11-3	1,2-Benzenedicarboxylic acid, dimethyl ester
U107	117-84-0	1,2-Benzenedicarboxylic acid, di-n-octyl ester
U070	95-50-1	Benzene, 1,2-dichloro-
U071	541-73-1	Benzene, 1,3-dichloro-
U072	106-46-7	Benzene, 1,4-dichloro-
U060	72-54-8	Benzene, 1,1'-(2,2-dichloro-ethylidene) bis[4-chloro-
U017	98-87-3	Benzene, (dichloromethyl)-
U223	26471-62-5	Benzene, 1,3-diisocyanatomethyl- (R,T)
U239	1330-20-7	Benzene, dimethyl- (I,T)
U201	108-46-3	1,3-Benzenediol
U127	118-74-1	Benzene, hexachloro-
U056	110-82-7	Benzene, hexahydro- (I)
U220	108-88-3	Benzene, methyl-
U105	121-14-2	Benzene, 1-methyl-2,4-dinitro-
U106	606-20-2	Benzene, 2-methyl-1,3-dinitro-
U055	98-82-8	Benzene, (1-methylethyl)- (I)
U169	98-95-3	Benzene, nitro- (I,T)
U183	608-93-5	Benzene, pentachloro-
U185	82-68-8	Benzene, pentachloronitro-
U020	98-09-9	Benzenesulfonic acid chloride (C,R)
U020	98-09-9	Benzenesulfonyl chloride (C,R)
U207	95-94-3	Benzene, 1,2,4,5-tetrachloro-
U061	50-29-3	Benzene, 1,1'-(2,2,2-trichloroethylidene)bis[4-chloro-
U247	72-43-5	Benzene, 1,1'-(2,2,2-trichloroethylidene)[4-methoxy-
U023	98-07-7	Benzene, (trichloromethyl)- (C,R,T)
U234	99-35-4	Benzene, 1,3,5-trinitro- (R,T)
U021	92-87-5	Benzidine
U202	[1]81-07-2	1,2-Benzisothiazol-3-(2H)-one,1,1-dioxide and salts
U203	94-59-7	1,3-Benzodioxole, 5-(2-propenyl)-
U141	120-58-1	1,3-Benzodioxole, 5-(1-propenyl)-
U090	94-58-6	1,3-Benzodioxole, 5-propyl-
U064	189-55-9	Benzo[rst] pentaphene
U022	50-32-8	Benzo[a]pyrene
U197	106-51-4	p-Benzoquinone
U023	98-07-7	Benzotrichloride (C,R,T)
U085	1464-53-5	2,2'-Bioxirane (I,T)
U021	92-87-5	[1,1'-Biphenyl]-4,4'-diamine
U073	91-94-1	[1,1'-Biphenyl]-4,4'-diamine, 3,3'-dichloro-
U091	119-90-4	[1,1'-Biphenyl]-4,4'-diamine, 3,3'-dimethoxy-
U095	119-93-7	[1,1'-Biphenyl]-4,4'-diamine, 3,3'-dimethyl-
U027	39638-32-9	Bis(2-chloroisopropyl) ether
U024	111-91-1	Bis(2-chloromethoxy) ethane
U028	117-81-7	Bis(2-ethylhexyl) phthalate
U225	75-25-2	Bromoform
U030	101-55-3	4-Bromophenyl phenyl ether
U128	87-68-3	1,3-Butadiene, 1,1,2,3,4,4-hexachloro-
U172	924-16-3	1-Butanamine, N-butyl-N-nitroso-
U031	71-36-3	1-Butanol (I)
U159	78-93-3	2-Butanone (I,T)
U160	1338-23-4	2-Butanone peroxide (R,T)
U053	4170-30-3	2-Butenal
U074	764-41-0	2-Butene, 1,4-dichloro- (I,T)

Table A-2 (cont'd)

Hazardous waste No.	Chemical Abstracts No.	Substance
U143	303-34-4	2-Butenoic acid, 2-methyl-, 7-[(2,3-dihydroxy-2-(1-methoxyethyl)-3-methyl-1-oxobutoxy)methyl]-2,3,5,7a-tetrahydro-1-pyrrolizin-1-yl ester, [1S-[1alpha(Z),7(2S, 3R),7aalpha]]-
U031	71-36-3	n-Butyl alchohol (I)
U136	75-60-5	Cacodylic acid
U032	13765-19-0	Calcium chromate
U238	51-79-6	Carbamic acid, ethyl ester
U178	615-53-2	Carbamic acid, methylnitroso-, ethyl ester
U097	79-44-7	Carbamic chloride, dimethyl-
U114	[1]111-54-6	Carbamodithioic acid, 1,2-ethanediylbis-, salts and esters
U062	2303-16-4	Carbamothioic acid, bis(1-methylethyl)-S-(2,3-dichloro-2-propenyl) ester
U215	6533-73-9	Carbonic acid, dithallium(1+) salt
U033	353-50-4	Carbonic difluoride
U156	79-22-1	Carbonochloridic acid, methyl ester (I,T)
U033	353-50-4	Carbon oxyfluoride (R,T)
U211	56-23-5	Carbon tetrachloride
U034	75-87-6	Chloral
U035	305-03-3	Chlorambucil
U036	12789-03-6	Chlordane
U026	494-03-1	Chlornaphazine
U037	108-90-7	Chlorobenzene
U039	59-50-7	p-Chloro-m-cresol
U041	106-89-8	1-Chloro-2,3-epoxypropane
U042	110-75-8	2-Chloroethyl vinyl ether
U044	67-66-3	Chloroform
U046	107-30-2	Chloromethyl methyl ether
U047	91-58-7	beta-Chloronaphthalene
U048	95-57-8	o-Chlorophenol
U049	3165-93-3	4-Chloro-o-toluidine, hydrochloride
U032	13765-19-0	Chromic acid, calcium salt
U050	218-01-9	Chrysene
U051	8021-39-4	Creosote
U052	1319-77-3	Cresols (Cresylic acid)
U053	4170-30-3	Crotonaldehyde
U055	98-82-8	Cumene (I)
U246	506-68-3	Cyanogen bromide
U197	106-51-4	2,5-Cyclohexadiene-1,4-dione
U056	110-82-7	Cyclohexane (I)
U057	108-94-1	Cyclohexanone (I)
U130	77-47-4	1,3-Cyclopentadiene, 1,2,3,4,5,5-hexachloro-
U058	50-18-0	Cyclophosphamide
U240	[1]94-75-7	2,4-D, salts and esters
U059	20830-81-3	Daunomycin
U060	72-54-8	DDD
U061	50-29-3	DDT
U062	2303-16-4	Diallate
U063	53-70-3	Dibenz[a,h]anthracene
U064	189-55-9	Dibenzo[a,i]pyrene
U066	96-12-8	1,2-Dibromo-3-chloropropane
U069	84-74-2	Dibutyl phthalate
U070	95-50-1	o-Dichlorobenzene
U071	541-73-1	m-Dichlorobenzene
U072	106-46-7	p-Dichlorobenzene
U073	91-94-1	3,3'-Dichlorobenzidine
U074	764-41-0	1,4-Dichloro-2-butene (I,T)
U075	75-71-8	Dichlorodifluoromethane
U078	75-35-4	1,1-Dichloroethylene
U079	156-60-5	1,2-Dichloroethylene
U025	111-44-1	Dichloroethyl ether
U081	120-83-2	2,4-Dichlorophenol
U082	87-65-0	2,6-Dichlorophenol
U240	[1]94-75-7	2,4-Dichlorophenoxyacetic acid, salts and esters
U083	78-87-5	1,2-Dichloropropane
U084	542-75-6	1,3-Dichloropropene
U085	1464-53-5	1,2:3,4-Diepoxybutane (I,T)
U108	123-91-1	1,4-Diethyleneoxide
U086	1615-80-1	N,N-Diethylhydrazine
U087	3288-58-2	O,O-Diethyl-S-methyl-dithiophosphate
U088	84-66-2	Diethyl phthalate
U089	56-53-1	Diethylstilbestrol
U090	94-58-6	Dihydrosafrole
U091	119-90-4	3,3'-Dimethoxybenzidine
U092	124-40-3	Dimethylamine (I)
U093	60-11-7	Dimethylaminoazobenzene
U094	57-97-6	7,12-Dimethylbenz[a]anthracene
U095	119-93-7	3,3'-Dimethylbenzidine
U096	80-15-9	alpha,alpha-Dimethylbenzylhydroperoxide (R)
U097	79-44-7	Dimethylcarbamoyl chloride
U098	57-14-7	1,1-Dimethylhydrazine
U099	540-73-8	1,2-Dimethylhydrazine
U101	105-67-9	2,4-Dimethylphenol
U102	131-11-3	Dimethyl phthalate
U103	77-78-1	Dimethyl sulfate
U105	121-14-2	2,4-Dinitrotoluene
U106	606-20-2	2,6-Dinitrotoluene
U107	117-84-0	Di-n-octyl phthalate
U108	123-91-1	1,4-Dioxane
U109	122-66-7	1,2-Diphenylhydrazine
U110	142-84-7	Dipropylamine (I)
U111	621-64-7	Di-n-propylnitrosamine
U001	75-07-0	Ethanal (I)
U174	55-18-5	Ethanamine, N-ethyl-N-nitroso-
U155	91-80-5	1,2-Ethanediamine, N,N-dimethyl-N'-2-pyridinyl-N'-(2-thienylmethyl)-
U067	106-93-4	Ethane, 1,2-dibromo-
U076	75-34-3	Ethane, 1,1-dichloro-
U077	107-06-2	Ethane, 1,2-dichloro-
U131	67-72-1	Ethane, hexachloro-
U024	111-91-1	Ethane, 1,1'-[methylenebis(oxy)]bis[2-chloro-
U117	60-29-7	Ethane, 1,1-oxybis- (I)
U025	111-44-4	Ethane, 1,1'-oxybis[2-chloro-
U184	76-01-7	Ethane, pentachloro-
U208	630-20-6	Ethane, 1,1,1,2-tetrachloro-
U209	79-34-5	Ethane, 1,1,2,2-tetrachloro-
U218	62-55-5	Ethanethioamide
U227	110-80-5	Ethanol, 2-ethoxy
U359	79-00-5	Ethane, 1,1,2-trichloro-
U173	1116-54-7	Ethanol, 2,2'-(nitrosoimino)bis-
U004	98-86-2	Ethanone, 1-phenyl-
U043	75-01-4	Ethene, chloro-
U042	110-75-8	Ethene, (2-chloroethoxy)-

Table A-2 (cont'd)

Hazardous waste No.	Chemical Abstracts No.	Substance
U166	130-15-4	1,4-Naphthoquinone
U167	134-32-7	alpha-Naphthylamine
U168	91-59-8	beta-Naphthylamine
U026	494-03-1	2-Naphthylamine, N,N'-bis(2-chloroethyl)-
U167	134-32-7	1-Naphthylenamine
U168	91-59-8	2-Naphthylenamine
U217	10102-45-1	Nitric acid, thallium(1+) salt
U169	98-95-3	Nitrobenzene (I,T)
U170	100-02-7	p-Nitrophenol
U171	79-46-9	2-Nitropropane (I,T)
U172	924-16-3	N-Nitrosodi-n-butylamine
U173	1116-54-7	N-Nitrosodiethanolamine
U174	55-18-5	N-Nitrosodiethylamine
U176	759-73-9	N-Nitroso-N-ethylurea
U177	684-93-5	N-Nitroso-N-methylurea
U178	615-53-2	N-Nitroso-N-methylurethane
U179	100-75-4	N-Nitrosopiperidine
U180	930-55-2	N-Nitrosopyrrolidine
U181	99-55-8	5-Nitro-o-toluidine
U193	1120-71-4	1,2-Oxathiolane, 2,2-dioxide
U058	50-18-0	2H-1,3,2-Oxazaphosphorin-2-amine, N,N-bis(2-chloroethyl)tetrahydro-, 2-oxide
U115	75-21-8	Oxirane (I,T)
U126	765-34-4	Oxiranecarboxyaldehyde
U041	106-89-8	Oxirane, (chloromethyl)-
U182	123-63-7	Paraldehyde
U183	608-93-5	Pentachlorobenzene
U184	76-01-7	Pentachloroethane
U185	82-68-8	Pentachloronitrobenzene (PCNB)
U242	87-86-5	Pentachlorophenol
U186	504-60-9	1,3-Pentadiene (I)
U187	62-44-2	Phenacetin
U188	108-95-2	Phenol
U048	95-57-8	Phenol, 2-chloro-
U039	59-50-7	Phenol, 4-chloro-3-methyl-
U081	120-83-2	Phenol, 2,4-dichloro-
U082	87-65-0	Phenol, 2,6-dichloro-
U089	56-53-1	Phenol, 4,4'-(1,2-diethyl-1,2-ethenediyl)bis-,(E)-
U101	105-67-9	Phenol, 2,4-dimethyl-
U052	1319-77-3	Phenol, methyl-
U132	70-30-4	Phenol, 2,2'-methylenebis[3,4,6-trichloro-
U170	100-02-7	Phenol, 4-nitro-
* U242	87-86-5	Phenol, pentachloro-
* U212	58-90-2	Phenol, 2,3,4,6-tetrachloro-
* U230	95-94-4	Phenol, 2,4,5-trichloro-
U231	88-06-2	Phenol, 2,4,6-trichloro-
U150	148-82-3	L-Phenylalanine, 4-[bis(2-chloroethyl) amino]-
U145	7446-27-7	Phosphoric acid, lead salt
U087	3288-58-2	Phosphorodithioic acid, O,O-diethyl-, S-methyl ester
U189	108-95-2	Phosphorus sulfide (R)
U190	85-44-9	Phthalic anhydride
U191	109-06-8	2-Picoline
U179	100-75-4	Piperidine, 1-nitroso-
U192	23950-58-5	Pronamide
U194	107-10-8	1-Propanamine (I,T)
U111	621-64-7	1-Propanamine, N-nitroso-N-propyl-
U110	142-84-7	1-Propanamine, N-propyl- (I)

Hazardous waste No.	Chemical Abstracts No.	Substance
U066	96-12-8	Propane, 1,2-dibromo-3-chloro-
U149	109-77-3	Propanedinitrile
U171	79-46-9	Propane, 2-nitro- (I,T)
U027	39638-32-9	Propane, 2,2'-oxybis[2-chloro-
U193	1120-71-4	1,3-Propane sultone
U235	126-72-7	1-Propanol, 2,3-dibromo-, phosphate (3:1)
U140	78-83-1	1-Propanol, 2-methyl- (I,T)
U002	67-64-1	2-Propanone (I)
U084	542-75-6	1-Propene, 1,3-dichloro-
U152	126-98-7	2-Propenenitrile, 2-methyl- (I,T)
U007	79-06-1	2-Propenamide
U243	1888-71-7	1-Propene, hexachloro-
U009	107-13-1	2-Propenenitrile
U008	79-10-7	2-Propenoic acid (I)
U113	140-88-5	2-Propenoic acid, ethyl ester (I)
U118	97-63-2	2-Propenoic acid, 2-methyl-, ethyl ester
U162	80-62-6	2-Propenoic acid, 2-methyl-, methyl ester (I,T)
*U233	93-72-1	Propionic acid, 2-(2,4,5-trichlorophenoxy)-
U194	107-10-8	n-Propylamine (I,T)
U083	78-87-5	Propylene dichloride
U148	123-33-1	3,6-Pyridazinedione, 1,2-dihydro
U196	110-86-1	Pyridine
U191	109-06-8	Pyridine, 2-methyl-
U237	66-75-1	2,4(1H,3H)-Pyrimidinedione, 5-[bis(2-chloroethyl)amino]-
U164	56-04-2	4-(1H)-Pyrimidinone, 2,3-dihydro-6-methyl-2-thioxo-
U180	930-55-2	Pyrrolidine, 1-nitroso-
U200	50-55-5	Reserpine
U201	108-46-3	Resorcinol
U202	81-07-2	Saccharin and salts
U203	94-59-7	Safrole
U204	7783-00-8	Selenious acid
U204	7783-00-8	Selenium dioxide
U205	7446-34-6	Selenium sulfide (R,T)
U015	115-02-6	L-Serine, diazoacetate (ester)
* U233	93-72-1	Silvex
U206	18883-66-4	Streptozotocin
U103	77-78-1	Sulfuric acid, dimethyl ester
U189	1314-80-3	Sulfur phosphide (R)
*U232	93-76-5	2,4,5-T
U207	95-94-3	1,2,4,5-Tetrachlorobenzene
U208	630-20-6	1,1,1,2-Tetrachloroethane
U209	79-34-5	1,1,2,2-Tetrachloroethane
U210	127-18-4	Tetrachloroethylene
* U212	58-90-2	2,3,4,6-Tetrachlorophenol
U213	109-99-9	Tetrahydrofuran (I)
U214	15843-14-8	Thallium(I) acetate
U215	6533-73-9	Thallium(I) carbonate
U216	7791-12-0	Thallium chloride
U217	10102-45-1	Thallium(I) nitrate
U218	62-55-5	Thioacetamide
U153	74-93-1	Thiomethanol (I,T)
U244	137-26-8	Thioperoxydicarbonic diamide, tetramethyl-
U219	62-56-6	Thiourea
U244	137-26-8	Thiuram
U220	108-88-3	Toluene
U221	25376-45-8	Toluenediamine
U223	26471-62-5	Toluene diisocyanate (R,T)

Table A-2 (cont'd)

Hazardous waste No.	Chemical Abstracts No.	Substance
U078	75-35-4	Ethene, 1,1-dichloro-
U079	156-60-5	Ethene, 1,2-dichloro-, (E)-
U210	127-18-4	Ethene, tetrachloro-
U228	79-01-6	Ethene, trichloro
U112	141-78-6	Ethyl acetate (I)
U113	140-88-5	Ethyl acrylate (I)
U238	51-79-6	Ethyl carbamate
U038	510-15-6	Ethyl 4,4'-dichlorobenzilate
U114	111-54-6	Ethylenebis(dithiocarbamic acid), salts and esters
U067	106-93-4	Etylene dibromide
U077	107-06-2	Ethylene dichloride
U359	110-80-5	Ethylene glycol monoethyl ether
U115	75-21-8	Ethylene oxide (I,T)
U116	96-45-7	Ethylene thiourea
U117	60-29-7	Ethyl ether (I)
U076	75-34-3	Ethylidene dichloride
U118	97-63-2	Ethyl methacrylate
U119	62-50-0	Ethylmethanesulfonate
U120	206-44-0	Fluoranthene
U122	50-00-0	Formaldehyde
U123	64-18-6	Formic acid (C,T)
U124	110-00-9	Furan (I)
U125	98-01-1	2-Furancarboxaldehyde (I)
U147	108-31-6	2,5-Furandione
U213	109-99-9	Furan, tetrahydro- (I)
U125	98-01-1	Furfural (I)
U124	110-00-9	Furfuran (I)
U206	18883-66-4	D-Glucopyranose, 2-deoxy-2(3-methyl-3-nitrosoureido)-
U126	765-34-4	Glycidylaldehyde
U163	70-25-7	Guanidine, N-methyl-N'-nitro-N-nitroso-
U127	18-74-1	Hexachlorobenzene
U128	87-68-3	Hexachlorobutadiene
U129	58-88-9	Hexachlorocyclohexane (gamma isomer)
U130	77-47-4	Hexachlorocyclopentadiene
U131	67-72-1	Hexachloroethane
U132	70-30-4	Hexachlorophene
U243	1888-71-7	Hexachloropropene
U133	302-01-2	Hydrazine (R,T)
U086	1615-80-1	Hydrazine, 1,2-diethyl-
U098	57-14-7	Hydrazine, 1,1-dimethyl-
U099	540-73-8	Hydrazine, 1,2-dimethyl-
U109	122-66-7	Hydrazine, 1,2-diphenyl-
U134	7664-39-3	Hydrofluoric acid (C,T)
U134	7664-39-3	Hydrogen fluoride (C,T)
U135	7783-06-4	Hydrogen sulfide
U096	80-15-9	Hydroperoxide, 1-methyl-1-phenylethyl- (R)
U136	75-60-5	Hydroxydimethylarsine oxide
U116	96-45-7	2-Imidazolidinethione
U137	193-39-5	Indeno[1,2,3-cd]pyrene
U139	9004-66-4	Iron dextran
U190	85-44-9	1,3-Isobenzofurandione
U140	78-83-1	Isobutyl alcohol (I,T)
U141	120-58-1	Isosafrole
U142	143-50-0	Kepone
U143	303-34-4	Lasiocarpine
U144	301-04-2	Lead acetate
U146	1335-32-6	Lead, bis(acetato-O)tetrahydroxytri-
U145	7446-27-7	Lead phosphate
U146	1335-32-6	Lead subacetate
U129	58-89-9	Lindane
U147	108-31-6	Maleic anhydride
U148	123-33-1	Maleic hydrazide
U149	109-77-3	Malononitrile
U150	148-82-3	Melphalan
U151	7439-97-6	Mercury
U152	126-98-7	Methacrylonitrile (I,T)
U092	124-40-3	Methanamine, N-methyl- (I)
U029	74-83-9	Methane, bromo-
U045	74-87-3	Methane, chloro-(I,T)
U046	107-30-2	Methane, chloromethoxy-
U068	74-95-3	Methane, dibromo-
U080	75-09-2	Methane, dichloro-
U075	75-71-8	Methane, dichlorodifluoro-
U138	74-88-4	Methane, iodo-
U119	62-50-0	Methanesulfonic acid, ethyl ester
U211	56-23-5	Methane, tetrachloro-
U153	74-93-1	Methanethiol (I,T)
U225	75-25-2	Methane, tribromo-
U044	67-66-3	Methane, trichloro-
U121	75-69-4	Methane, trichlorofluoro-
U123	64-18-6	Methanoic acid (C,T)
U154	67-56-1	Methanol (I)
U155	91-80-5	Methapyrilene
U142	143-50-0	1,3,4-Metheno-2H-cyclobuta[cd]pentalen-2-one,1,1a,3,3a,4,5,5,5a,5b,6-decachloro-octahydro-
U247	72-43-5	Methoxychlor
U154	67-56-1	Methyl alcohol (I)
U029	74-83-9	Methyl bromide
U186	504-60-9	1-Methylbutadiene (I)
U045	74-87-3	Methyl chloride (I,T)
U156	79-22-1	Methylchlorocarbonate (I,T)
U226	71-55-6	Methylchloroform
U157	56-49-5	3-Methylcholanthrene
U158	101-14-4	4,4'-Methylenebis(2-chloroaniline)
U068	74-95-3	Methylene bromide
U080	75-09-2	Methylene chloride
U159	78-93-3	Methyl ethyl ketone (MEK)(I,T)
U160	1338-23-4	Methyl ethyl ketone peroxide (R,T)
U138	74-88-4	Methyl iodide
U161	108-10-1	Methyl isobutyl ketone (I)
U162	80-62-6	Methyl methacrylate (I,T)
U163	70-25-7	N-Methyl-N'-nitro-N-nitrosoguanidine
U161	108-10-1	4-Methyl-2-pentanone (I)
U164	56-04-2	Methylthiouracil
U010	50-07-7	Mitomycin C
U059	20830-81-3	5,12-Naphthacenedione, (8S-cis)-8-acetyl-10-[(3-amino-2,3,6-trideoxy-alpha-L-lyxo-hexopyranosyl)oxy]-7,8,9,10-tetrahydro-6,8,11-trihydroxy-1-methoxy-
U165	91-20-3	Naphthalene
U047	91-58-7	Naphthalene, 2-chloro-
U166	130-15-4	1,4-Naphthalenedione
U236	72-57-1	2,7-Naphthalenedisulfonic acid, 3,3'-[(3,3'-dimethyl-(1,1'-biphenyl)-4,4'diyl)]-bis (azo) bis(5-amino-4-hydroxy)-, tetrasodium salt

Table A-2 (cont'd)

Hazardous waste No.	Chemical Abstracts No.	Substance
U328	95-53-4	o-Toluidine
U353	106-49-0	p-Toluidine
U222	636-21-5	o-Toluidine hydrochloride
U011	61-82-5	1H-1,2,4-Triazol-3-amine
U226	71-55-6	1,1,1-Trichloroethane
U227	79-00-5	1,1,2-Trichloroethane
U228	79-01-6	Trichloroethylene
U121	75-69-4	Trichloromonofluoromethane
* U230	95-95-4	2,4,5-Trichlorophenol
* U231	88-06-2	2,4,6-Trichlorophenol
U234	99-35-4	sym-Trinitrobenzene (R,T)
U182	123-63-7	1,3,5-Trioxane, 2,4,6-trimethyl-
U235	126-72-7	Tris(2,3-dibromopropyl) phosphate
U236	72-57-1	Trypan blue
U237	66-75-1	Uracil mustard
U176	759-73-9	Urea, N-ethyl-N-nitroso-
U177	684-93-5	Urea, N-methyl-N-nitroso-
U043	75-01-4	Vinyl chloride
U248	81-81-2	Warfarin, when present at concentrations of 0.3% or less
U239	1330-20-7	Xylene (I)
U200	50-55-5	Yohimban-16-carboxylic acid, 11,17-dimethoxy-18-[(3,4,5-trimethoxybenzoyl) oxy]-, methyl ester
U249	1314-84-7	Zinc phosphide, when present at concentrations of 10% or less.

[1]CAS Number given for parent compound only.

* These wastes are also designated as F027 wastes. See Table A-1.

Table A-2 (cont'd)

Industry and EPA hazardous waste No.	Hazardous waste	Hazard code
Generic:		
F001	The following spent halogenated solvents used in degreasing: Tetrachloroethylene, trichloroethylene, methylene chloride, 1,1,1-trichloroethane, carbon tetrachloride, and chlorinated fluorocarbons; all spent solvent mixtures/blends used in degreasing containing, before use, a total of ten percent or more (by volume) of one or more of the above halogenated solvents or those solvents listed in F002, F004, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.	(T)
F002	The following spent halogenated solvents: Tetrachloroethylene, methylene chloride, trichloroethylene, 1,1,1-trichloroethane, chlorobenzene, 1,1,2-trichloro-1,2,2-trifluoroethane, ortho-dichlorobenzene, trichlorofluoromethane, and 1,1,2-trichloroethane; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above halogenated solvents or those listed in F001, F004, or F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.	(T)
F003	The following spent non-halogenated solvents: Xylene, acetone, ethyl acetate, ethyl benzene, ethyl ether, methyl isobutyl ketone, n-butyl alcohol, cyclohexanone, and methanol; all spent solvent mixtures/blends containing, before use, only the above spent non-halogenated solvents; and all spent solvent mixtures/blends containing, before use, one or more of the above non-halogenated solvents, and, a total of ten percent or more (by volume) of one or more of those solvents listed in F001, F002, F004, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.	(I)*
F004	The following spent non-halogenated solvents: Cresols and cresylic acid, and nitrobenzene; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above non-halogenated solvents or those solvents listed in F001, F002, and F005; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.	(T)
F005	The following spent non-halogenated solvents: Toluene, methyl ethyl ketone, carbon disulfide, isobutanol, pyridine, benzene, 2-ethoxyethanol, and 2-nitropropane; all spent solvent mixtures/blends containing, before use, a total of ten percent or more (by volume) of one or more of the above non-halogenated solvents or those solvents listed in F001, F002, or F004; and still bottoms from the recovery of these spent solvents and spent solvent mixtures.	(I,T)
F006	Wastewater treatment sludges from electroplating operations except from the following processes: (1) Sulfuric acid anodizing of aluminum; (2) tin plating on carbon steel; (3) zinc plating (segregated basis) on carbon steel; (4) aluminum or zinc-aluminum plating on carbon steel; (5) cleaning/stripping associated with tin, zinc and aluminum plating on carbon steel; and (6) chemical etching and milling of aluminum.	(T)
F019	Wastewater treatment sludges from the chemical conversion coating of aluminum.	(T)
F007	Spent cyanide plating bath solutions from electroplating operations.	(R, T)
F008	Plating bath residues from the bottom of plating baths from electroplating operations where cyanides are used in the process.	(R, T)
F009	Spent stripping and cleaning bath solutions from electroplating operations where cyanides are used in the process.	(R, T)
F010	Quenching bath residues from oil baths from metal heat treating operations where cyanides are used in the process.	(R, T)
F011	Spent cyanide solutions from salt bath pot cleaning from metal heat treating operations.	(R, T)
F012	Quenching waste water treatment sludges from metal heat treating operations where cyanides are used in the process.	(T)
F024	Wastes, including but not limited to, distillation residues, heavy ends, tars, and reactor clean-out wastes from the production of chlorinated aliphatic hydrocarbons, having carbon content from one to five, utilizing free radical catalyzed processes. [This listing does not include light ends, spent filters and filter aids, spent dessicants, wastewater, wastewater treatment sludges, spent catalysts, and wastes listed in Section 261.32.].	(T)
F028	Residues resulting from the incineration or thermal treatment of soil contaminated with EPA Hazardous Waste Nos. F020, F021, F022, F023, F026, and F027.	(T)

APPENDIX B

IDENTIFYING RCRA CHARACTERISTIC HAZARDOUS WASTES

EPA has identified four characteristics which cause a waste to be regulated as a hazardous waste: ignitable, corrosive, reactive, and extraction procedure (EP) toxic. For each characteristic, EPA has developed approved methods for determining whether a waste is hazardous. A brief description of each characteristic and applicable tests follows. The specific definitions of these characteristics are specified in 40 CFR 261, Subpart C.

CHARACTERISTIC OF IGNITABILITY:

A waste exhibits the characteristic of ignitability if a representative sample of the waste is easily combustible or flammable. Examples of these ignitable wastes include paint wastes, certain degreasers, and solvents. The specific characteristics of an ignitable waste include the following properties:

- A liquid that has a flash point of less than 140°F as determined by a specific test method. This does not include aqueous solutions containing less than 24% alcohol by volume.
- It is not a liquid but is capable of causing fire through friction, absorption of moisture, or spontaneous chemical changes under standard temperature and pressure conditions.
- It is an ignitable compressed gas.
- It is an oxidizer.

A waste exhibiting any of these characteristics of ignitablility is identified for regulatory purposes with an EPA hazardous waste number of D001.

CHARACTERISTIC OF CORROSIVITY

A waste exhibiting the characteristic of corrosivity will dissolve metal or burn the skin. Examples of corrosive wastes include waste rust removers, waste acids and alkaline solutions, and waste battery acids. The specific characteristics of a corrosive waste include the following:

- o An aqueous waste with a pH less than or equal to 2.0 or greater than or equal to 12.5 as determined by an EPA-approved method.

- A liquid which corrodes steel at a rate greater than 6.35 millimeters (0.250 inches) per year at a temperature of 130°F as determined by specific test methods.

A waste exhibiting any of these characteristics of corrosivity is identified for regulatory purposes with an EPA hazardous waste number of D002.

CHARACTERISTIC OF REACTIVITY

A waste exhibiting the characteristic of reactivity is one that is unstable or undergoes rapid or violent chemical reactions with water or other material. Examples of reactive wastes include cyanide plating wastes, waste bleaches, and other waste oxidizers. The specific characteristics of a reactive waste include the following:

- It is normally unstable and readily undergoes violent changes without detonating.
- It reacts violently with water.
- It forms a potentially explosive mixture with water.
- It generates toxic gases, vapors, or fumes when mixed with water.
- It is a cyanide or sulfide bearing waste which can generate toxic gases, vapors, or fumes when exposed to pH conditions between 2.0 and 12.5.
- It is capable of detonation or a explosive reaction under standard temperature and pressure conditions or if subjected to a strong initiating source or if heated.

A waste exhibiting any of these reactive characteristics is identified for regulatory purposes with an EPA hazardous waste number of D003.

CHARACTERISTIC OF EP TOXICITY

EPA has designed a leaching test, called the Extraction Procedure (EP), to measure the amount of toxic materials that can be extracted from the waste under specific conditions. If the extract obtained from the test exceeds set concentration limits for certain constituents, the waste will be

considered hazardous. The EP toxicity test is used to determine whether leachate from disposal of a particular hazardous waste will pollute ground water.

There are 14 constituents that EPA has established concentration limits for in the EP toxicity test, including eight metals and six pesticides. Each of these contaminants has been assigned a specific EPA hazardous waste number. These contaminants, their associated EPA hazardous waste number, and the established concentration limits are listed in Table B-1. If a representative sample of a waste if found to contain any of the contaminants listed in this table at a concentration greater than or equal to those limits specified, the waste is considered an EP toxic hazardous waste.

APPENDIX C: REFERENCES AND CONTACTS

FEDERAL REGULATIONS

Code of Federal Regulations: The RCRA regulations addressed in this manual are referenced in the Code of Federal Regulations, Title 40, Parts 260 to 272.

Copies of the Code of Federal Regulations are available in most large public libraries. They may also be purchased from the Government Printing Office by calling (202) 783-3238.

RCRA Hotline: As a public service, the U.S. Environmental Protection Agency has provided a RCRA Hotline where anyone can call for technical or administrative information regarding the RCRA regulations.

The phone number for the RCRA Hotline is: 1-800-424-9346 (Hours from 8:30 a.m. to 4:30 p.m. EST, Monday through Friday)

References:

(1) "Understanding the Small Quantity Generator Rules: A Handbook for Small Business", published by EPA, Office of Solid Waste and Emergency Response, September, 1986. (EPA Publication No. EPA/530-SW-86-019) This is a handy, easy-to-read, reference for understanding the small quantity generator regulations.

(2) Handbook of Hazardous Waste Management for Small Quantity Generators, by Russell.W. Phifer and William .R McTigue, Jr., Lewis Publishers, Inc., 1988. This book provides a guide to the small quantity generator requirements, waste types generated from various industries, liability considerations, and onsite and offsite management of hazardous wastes.

STATE REGULATIONS

Administrative Rules of Montana: The state regulations addressed in this manual can be found in the Administrative Rules of Montana, Rule 16, Chapter 44.

Montana Department of Health and Environmental Science (DHES): The DHES can provide assistance to anyone with questions or concerns about the federal and state regulations, compliance issues, or waste management practices.

For further information, contact the DHES, Solid and Hazardous Waste Bureau, Room B201, Cogswell Building, Helena, Montana, 59620. The phone number is: (406) 444-2821.

WASTE MANAGEMENT

Contacts:

Waste Exchange Program - This program, sponsored by the Montana Chamber of Commerce, is an informational exchange program designed bring together generators and users of a waste which have a reuse or recycling value. The program is intended to put generators in contact with waste users that can reuse the waste as a feedstock or substitute material in their operations. The Chamber of Commerce publishes a free newletter which lists both waste generators with potentially reusable waste materials, and users who are in the market for a particular reusable waste material.

The state chamber can be contacted at 110 Neill Avenue, Helena, Montana, 59601. The telephone number is (406) 442-2405.